

# Carbon Dioxide 100/a

Order No. 81 01 811

## Application Range

Standard Measuring Range:	100 to 3,000 ppm
Number of Strokes n:	10
Time for Measurement:	approx. 4 min.
Standard Deviation:	± 10 to 15 %
Color Change:	white → pale violet/ blue violet

## Ambient Operating Conditions

Temperature:	15 to 25 °C
Absolute Humidity:	max. 23 mg H <sub>2</sub> O / L

## Reaction Principle



## Cross Sensitivity

No influence on the reading by 10 ppm hydrogen sulfide and 2 ppm sulfur dioxide.



*Northside Sales, Co.*

Safety & Industrial Products

800-467-9005